Schedule of Accreditation issued by

United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

0170

Type C

Assessment Manager: MS5 Page 1 of 4

Schedule of Accreditation

issued by

United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

0170 Type C Inspection Body

Accredited to ISO/IEC 17020:2012 Element Materials Technology Environmental UK Limited Issue No: 028 Issue date: 02 November 2020

Inspection performed by the Organisation at/from the locations specified

Location details		Activity	Location code
Address Element Materials Technology Environmental UK Limited Oldbury Power Station Oldbury Naite Thornbury BS35 1RQ	Local contact Mr Abdul Selemani Tel: +44 (0)1454 893539 Email: abdul.selemani@element.com	Asbestos: Surveying	Ob
Address Element Materials Technology Environmental UK Limited Trawsfynydd Power Station Blaenau Ffestiniog Gwynedd Wales LL41 4DT United Kingdom	Local contact Mr David Howarth Tel: +44 (0)1766 543548 Email: david.howarth@element.com	Asbestos: Surveying	Tf
Address Element Materials Technology Environmental UK Limited Wylfa Power Station Cemaes Bay LL67 0DH	Local contact Mr Andrew Glover Tel: +44 (0) 7472 877386 Email: andrew.glover@exova.com	Asbestos: Surveying	Wf
Address Element Materials Technology Environmental UK Limited Berkeley Power Station Berkeley G13 9PA	Local contact Mr David Rolfe Tel: +44 (0)7921 511417 Email: david.rolfe@element.com	Asbestos: Surveying	Bk

Address Element Materials Technology Environmental UK Limited Dungeness A Power Station

Assessment Manager: MS5 Page 2 of 4

Schedule of Accreditation issued by United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK O170 Type C Inspection Body Accredited to ISO/IEC 17020:2012

Inspection performed by the Organisation at/from the locations specified $% \left(1\right) =\left(1\right) \left(1\right) \left$

DETAIL OF ACCREDITATION

Field of Inspection

Type and Range of Inspection

Methods and Procedures

Location

Code

Assessment Manager: MS5 Page 4 of 4